


International Paper\Air Handling Area\Fan Set 28712 \Fan\NDE 45\Overall velocity >600



Main Cursor	= Not Active	Machine	Fan
	= Not Active	Type :	Blower
Delta Cursor	= Not Active	ISO Class	Group 1 (ISO10816-3)
	= Not Active	Power :	600 HP
		Speed	1750 RPM

Date	Time	Event	Comment
6/18/2003	11:44:07 AM	Lubricant leakage	
8/1/2001	1:18:52 PM	Excess lubrication	
4/23/2001	1:50:20 PM	Component has visible cracks	

Vibration levels increase, recommend FFT analysis to determine cause