



Main Cursor	= Not Active	(1200.00) Looseness 1X	1200.00
	= Not Active	(2400.00) Looseness 2X	2400.00
Delta Cursor	= Not Active	(3600.00) Looseness 3X	3600.00
	= Not Active	(4800.00) Looseness 4X	4800.00
RPM	= 1200		
rms	= 0.11		